

GRAYS HARBOR COUNTY

| | | | | | |
|------------------|---|-------|--------------------------------|-------|------------------------------------|
| SITE ID: | SAGINAW MILL | | Cleanup Site ID: 2878 | | FS ID: 1125 |
| | Alternate Name(s): SAGINAW MILL | | | | |
| LOCATION: | WRIA: 22 | | Lat/Long: 46.966 -123.814 | | View Vicinity Map |
| Address: | T17N R9W S16 | | Township | Range | Section |
| | ABERDEEN | 98520 | 17N | 9W | 16 |
| | | | | | Legislative District: 19 |
| | | | | | Congressional District: 6 |
| STATUS: | Construction Complete-Performance Monitoring | | Rank: 1 | | View Site Web Page |
| | Responsible Unit: Southwest | | Site Manager: Landskron, Jason | | Statute: MTCA |
| | Is Brownfield? Yes | | Has Environmental Covenant? | | Is PSI Site? |
| | NFA Received? | | NFA Date: | | NFA Reason: |

ASSOCIATED CLEANUP UNIT(s)

| culID | Cleanup Unit Name | Unit Type | Process Type | Unit Status | Size (Acres) | ERTS ID |
|-------|-------------------|-----------|---------------------------------|---|--------------|---------|
| 663 | SAGINAW MILL | Upland | Ecology-supervised or conducted | Cleanup Complete - Active O&M/Monitoring ongoing | | |

SITE ACTIVITIES:

| Applies to: | Related ID (Unit-LUST-VCP) | Activity Display Name | Status | Start Date | End Date | Legal Mechanism | Performed By | Project Manager |
|------------------------------|-------------------------------|---|-----------|------------|------------|---------------------|------------------|------------------|
| CleanupSite | | Early Notice Letter(s) | | | 6/12/1991 | | | Southwest Region |
| CleanupSite | | Site Hazard Assessment/Federal Site Inspection | Completed | 6/24/1993 | 6/24/1993 | | Local Government | Heggen, Dick |
| CleanupSite | | Hazardous Sites Listing/NPL | | | 9/7/1993 | | | Southwest Region |
| CleanupSite MilestoneType | | Ecology Remedial Investigation and/or Feasibility Study | Completed | 8/1/1996 | 6/15/1997 | | Ecology | Reale, Dom |
| CleanupSite MilestoneType | | Ecology Cleanup Action-Engineering Design | Completed | 6/1/1998 | 10/19/1999 | | Ecology | Reale, Dom |
| CleanupSite MilestoneType | | Ecology Cleanup Construction | Completed | 7/15/1999 | 6/19/2000 | | Ecology | Reale, Dom |
| CleanupSite MilestoneType | | Ecology Post-Cleanup O & M | Completed | 6/19/2000 | 4/6/2015 | Governmental Action | PLP | Reale, Dom |
| CleanupSite MilestoneType | | Ecology Interim Action | Completed | 10/15/1995 | 11/15/1995 | | Ecology | Reale, Dom |

AFFECTED MEDIA & CONTAMINANTS:

Media:

| Contaminant: | Ground Water | Surface Water | Soil | Sediment | Air | Bedrock |
|------------------------------------|--------------|---------------|------|----------|-----|---------|
| Conventional Contaminants, Organic | RB | | RB | | | |
| Petroleum Products-Unspecified | | | RB | | | |

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014